


Review of Diamond SR RF Operation and Upgrades



Morten Jensen
on behalf of
Diamond Storage Ring RF Group



Agenda

Stats

X-ray and LN2 pressure results

Cavity Failure


Conditioning in the RFTF

Cavity Simulations


IOT Upgrade

Helium Refrigerator update

RF MTBF of beam loss and Number of beam trips per run







Cavity 1 only
1.8 MV typical
Many trips in Run 1 to find acceptable voltage
Cavity 3 Installed



Overall MTBF STILL dominated by Cavity trips

X-ray measurements on the cavities



Detuning (i.e. increasing power for constant beam does not change intensity

Total intensity is varies with both power and voltage

LN2 supply pressure stability improved

LN2 Supply pressure
Peak to peak reduced
from ~ 1.5 bar to 0.25 bar
Further optimisation likely

Tuner position
reduced but most
noticeable on cavity 1

LN2 Pressure stability improved by the installation of
pressure and level control valves on the LN2 supply tank
Ongoing investigation to determine residual perturbation




Cavity 2 Failure

Cavities 1 and 2 installed and being warmed up over Christmas. Warming up the cavities requires the use of electrical heaters. Procedure and Manual did not include turning off heaters. Heaters were not interlocked.

→ **Heaters were left on!**

First sign: Leak from helium can to insulation vacuum




CLTS on Cavity 2 Fail




Cavity 2 Failure

Investigation revealed:

- Both Helium level sensors not functioning
- Main pickup and waveguide coax cables have short circuit (both in helium can).
- Some of the temperature sensors on the niobium cell have been unsoldered.




Helium level probes with blue 'plastic' insulation which has melted



Vacuum seal has failed and indium has melted

Cavity 2 Failure

Additional observations not related to the increase in temperature




Radial groove from original BCP etch




Copper Plating Problems




Peeling copper plating on most pickups and missing plating inside the cups




Marks on copper plating in the waveguide.
Staining or tracking marks?



Damaged plating in waveguide section



Copper Plating Problems



Discolouration of waveguide components and of the gasket



Staining or damaged plating in the corners of the waveguide

5 - 8 January:

Cavity 2 removed from tunnel and make up vessel installed.

9 - 10 January:

Cavity 1 cooled down – noticed that no level sensors were usable and RF pickup cables short circuited.

10 January (Sunday night):

Controlling level by controlling total inventory. RF control via spare RF cable on the beam pipe.

11 January:


Machine start-up

Then move on to Radiofrequency Test Facility commissioning, cavity installation and conditioning in RFTF.



Conditioning of cavity 3 inside RFTF

Initial conditioning in February 2010. Gradual increase in cavity voltage and power dips caused by fast vacuum protection during conditioning can be seen.




Forward power

Vacuum spikes during conditioning



Soak test in April. Time scale is kept the same as last slide.
Improvement in long term performance can be seen clearly.



~ 3 days




Infrared pictures of RF window during conditioning


84KW forward power, cavity on resonance

55KW forward power, detune angle -60degree

RF Window 28 degree





Waveguide walls



Window heated up to 30 degree


2 Q0 measurement showing Q0 drop at low voltage



Cavity partial warm up experiment


Partial warm up to 28K to release hydrogen.

Warm up can help with the vacuum but not necessary the long term performance of the cavity




Vacuum is better after partial warm up. But many vacuum spikes appeared. Some spikes triggered protection.


PMT signal during conditioning



PMT signal showing probe blip



X-ray starts around 1.5MV.




Probe problem

1. Main probe and e- pickup have failed.
2. Cavity 2 and 3 both suffer probe blips. Cavity 1 under investigation.
3. Probe blips happen with and without beam.
4. Probes don't have blips at the same time.
5. Probe blips don't always trip the beam.
6. Very high amplitude.
7. Not successful to filter it out. (Band pass filter, DC block)
8. Not successful with bias voltage.


Cavity Signal

Spare pickup



Another spare pickup




Observed probe 'blips' kicked off wake field simulation of the RF probes



ϕ 240 mm beam pipe **Port-1**





Snapshot E-Field at t=1.05 ns for 10 & 3 mm bunches, yz-plane



The maximum field value is clamped at 100 V/m in both cases.

The field at the DLS pick-up has decayed by the time the bunch passes the CLS pick-up and therefore appears to be lower.







The EM signal induced by the beam propagates in many modes through the pick-ups.

Factor of 100 increase in field


For 10 mm bunch the voltage induced between the conductors is very low at 0.003 V for DLS pickup and lower still for CLS design



3 mm bunch
 ~ 7 V between conductors for 250 mA 600 bunches. DLS probe has 4 x CLS voltage




Frequency content of Voltage Signal



Summary:

Diamond beam ($\sigma = 3 \text{ mm}$) excites stronger signal in the pick-ups compared to the CLS and CESR ($\sigma = 10 \text{ mm}$) beams for the same charge.




The DLS Pick-ups have larger diameters and so the signal induced will be stronger.


Risk of breakdown and wakefield effects are greater for the DLS pickup but unlikely to be the main reason for our beam trips.




Multipactor simulation of the DLS Cavity & Waveguide



To establish TW fields in the waveguide





Development of Multipactor, P = 200 kW PIC Solver



Exponential growth of number of particles indicate multipactor

Particle Number vs. Time





CST model for Multipactor study near Coupling tongue

Coupling tongue

Electron Source definition

Source type	Face
Particle type	electron
Charge	-1.602177e-019 C
Mass	9.109389e-031 kg
Type	Energy
Value	5 eV
Spread	5 %
Model	Fixed
Current	1 A




TM010 E field from Eigen mode solver near coupling tongue



Preliminary tracking solver Results

Eigen mode field scaled to 1 MV across cavity

Solver Statistics (Trk)-Particle vs. Time



DLS IOT Upgrade from TED to E2V IOTs

TED IOT



E2V IOT



DLS IOT Upgrade from TED to E2V IOTs

- Successfully upgraded Systems 1 and 2 from TED to e2v IOTs during Christmas 2009 shutdown

Advantages

- Reduced IOT trips
- Simple tuning and setup with indexed settings
- Built in radiation shields no lead required
- Ion Pump readily recovers vacuum during initial filament start up

Differences

- Cavities built around IOT
- Cathode at the top inside the input cavity
- Network analyser not required for tuning



Current IOT Operating Hours

	e2v					
	S/N	Hrs in user operation	Hrs (Spares)	Hrs (Failed)	Status	Notes
IOT11	224-0711	2467				
IOT12	290-0939	996				
IOT13	211-0647	18976				
IOT14	212-0647	18839				
IOT31	289-0938	4269				
IOT32	287-0931	4264				
IOT33	273-0907	5624				
IOT34	288-0935	4265				
IOT22	223-0710	15327			Grid emission	Waiting for grid outgassing
	210-0647	14853			Suspect	Under investigation for tripping
IOT21	268-0851		1040		Spare	
	205-0639			1219	Failed	During initial commissioning
	222-0710				Spare	Unused
	269-0904				Spare	Unused
	277-0909		510		Spare	

2009: 19 trips during 4300 operational hours (mostly TED IOTs)


2010: 9 x ISCs: 5 during initial run with new tubes
4 in a quick succession on single IOT



Typical Operating Conditions (S/N 268-0851)



HV (kV)	Pin (W)	Pout (kW)	I b (A)	Eff (%)	Gain (dB)	
-35	159	35	2.0	50	23.5	
-35	234	50	2.6	55	23.31	
-35	352	80	3.29	67	23.4	

Efficiency During Initial Tune/Set Up (S/N 268-0851)



Current measurement board affected by change from TED to E2V IOTs


Original e2v configuration




-36kV return
Now through
IOT Body
and HVPS I
input





Current measurement board affected by change from TED to E2V IOTs



Earth current directed through IOT current transducers



Body current components removed



Problem:

Speed sensing of the warm turbine has occasionally become erratic without prior warning.

Repair:

After ensuring that the fibre optic cable was properly mounted, part of the signal conditioning box was changed.

The problem reoccurred. The frequency to analogue converter was then replaced. There has been no reoccurrence.

Frequency to analogue converter

Signal conditioner

Fibre optic input



Thank you for your attention

